

ELITE*pro* SP

Calibration Stability and Traceability Statement

January, 2012



The robust, inherently stable electrical design makes the **ELITE***pro* SP highly resistant to aging and drift phenomena that cause calibration errors. Our experience with this device indicates that the calibration of the **ELITE***pro* SP remains within the manufacturer's specifications for a minimum of three years, and in most cases factory recalibration is never required.

The calibration of each **ELITE***pro* SP is traceable to the National Institute of Standards and Technology (NIST) using these reference instruments.

- Hewlett Packard 34401A Multimeter, Serial # MY44008125,
- Hewlett Packard 34401A Multimeter, Serial # MY45000644